


# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016


## Exhibit-B: Inventory of Local Airport & Heliports within 10NM



# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-C: Local Wind Patterns at Kansas City International Airport (2002-2011) & Local Magnetic Declination


### KANSAS CITY INTERNATIONAL AIRPORT 10-year summary: 2002 - 2011



Local wind speed and direction variability  
10-year summary from NOAA




HeliExperts site specific Wind & Compass  
Rose for both Magnetic and True North



Site magnetic declination as of 8/27/2016

# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-D: Local Airspace Overlay (Kansas City Sectional)




# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-E: Supporting Airspace for VFR Approach/Departure Paths




# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-F: Proposed Approach/Departure Paths Airspace Overlay (High Altitude View)




# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-G: Proposed Approach/Departure Path Topographical Overlay



# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-H: 003° / 183° Approach/Departure Path Topographical Profile




**HELIXPerts INTERNATIONAL LLC.**  
Formerly Raymond A. Syme & Associates  
Veteran Owned and Operated

**Aeronautical Consulting Services**  
28 Baruch Drive, Long Branch, New Jersey 07740  
Phone: (732) 870-8883 Fax: (732) 870-8885  
[www.helixpertsinternational.com](http://www.helixpertsinternational.com) ■ [info@helixp.com](mailto:info@helixp.com)


# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-I: 003° / 183° Approach/Departure Path Topographical Profile



# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-J: Proposed Approach/Departure Paths Airspace Overlay (Low Altitude View)




# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-K: Proposed Heliport Site Orientation and Dimensional Integration



# National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

## Exhibit-L: Proposed Heliport Layout




 **HELIEXPERTS INTERNATIONAL LLC.**  
Formerly Raymond A. Syms & Associates  
**Aeronautical Consulting Services**  
Veteran Owned and Operated  
28 Baruch Drive, Long Branch, New Jersey 07740  
Phone: (732) 870-8883 Fax: (732) 870-8885  
[www.heliexpertsinternational.com](http://www.heliexpertsinternational.com) | [info@heliexp.com](mailto:info@heliexp.com)

**National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016**  
**Exhibit-M: Proposed Heliport Conceptual Design**


Conceptual  
Design

 **HELIXPerts INTERNATIONAL LLC.**  
Formerly Raymond A. Syme & Associates  
**Aeronautical Consulting Services**  
28 Baruch Drive, Long Branch, New Jersey 07740  
Phone: (732) 870-8883 Fax: (732) 870-8885  
[www.heliexpertsinternational.com](http://www.heliexpertsinternational.com) ■ [info@heliexp.com](mailto:info@heliexp.com)




**Elevated Mound Area**

TLOF profile with elevated perimeter & Lead-In light spacing




National Golf Club of Kansas City Feasibility & Site Selection Report: 9/8/2016

Exhibit-N: Proposed Heliport Conceptual Design



## Exhibit G



Allen Way – View facing southwest



Corner of Birkdale Dr. and Allen Way – View northwest



Corner of Birkdale Dr. and Allen Way – View facing east



Corner of Birkdale Dr. and Allen Way – View facing northeast